



1/15








FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20





FIG. 21



Method

Having Gaps Between Metal Lines and Metal Layers
Inventor(s): ZHAO, ET AL.; Ser. No.: 09/665,422; Page 5 of 15






Fig. 29




Fig. 75




Fig. 76




Fig. 77




Fig. 78




Fig. 79






Fig. 80





9/15




Fig. 5J




Fig. 5H




Fig. 5I






Fig. 5L



II / 15






Fig. 10




Fig. 11




Fig. 12




Fig. 6A




Fig. 6B






Fig. 6C

17/15



14 / 15



15 / 15




Fig. 80




Fig. 79